Carrier Customer Bulletin



FRONTIER COMMUNICATIONS PARENT, INC 401 MERRITT 7 CORPORATE PARK NORWALK CT 06851

SHORT TERM PUBLIC NOTICE UNDER RULE 51.333 (a)

Date of Public May 1, 2023 **Notice:** Notice #: CCBFTRO2123 **Carrier Name and** CTSI, Inc.-, 401 Merritt 7 Corporate Park Norwalk, CT 06851 Address: Lee Abrams Sr Network Engineer-Planning Contact: Email: Leon.Abrams@FTR.com Phone: 518-773-6073 **Implementation** Upon FCC approval, with the project completion targeted on or after September 1, 2023 Date:

Description of Network Changes Planned:

CTSI Inc.- announces that it intends to retire it's Harrisburg PEO Switch and associated remote wire centers listed below:

Wire Center	Address	CLLI
Harrisburg, PA	31 S 31ST ST Harrisburg, PA 17111	HRBGPA29PS0

On or after September 1, 2023, the Harrisburg, pa PEO switch, and associated remotes will be retired and removed from Frontier's network as part of its ongoing efforts to modernize the network.

The Exchange Codes (NXX) identified in Table B in Numbering Plan Area (NPA) 717 currently residing in the Harrisburg PA POI located at 31 S 31ST ST Harrisburg, PA 17111 will be moved to the Harrisburg PA PEO virtual switch located at 31 S 31ST ST Harrisburg, PA 17111 (see details in Table A below).

The native NPA/ NXX codes assigned to the Harrisburg PA POI will be rehomed upon decommissioning of the switch and reflected in the Local Exchange Routing Guide (LERG) for the Harrisburg PA PEO switch. This will occur on or after June 1, 2023.

Carrier Customer Bulletin



FRONTIER COMMUNICATIONS PARENT, INC 401 MERRITT 7 CORPORATE PARK NORWALK CT 06851

Description of Reasonably Foreseeable Impact of the Planned Changes:

The native NPA NXX belonging to the Harrisburg, PA PEO switch and associated remotes will be rehomed upon decommissioning of the switch and reflected in the Local Exchange Routing Guide (LERG) for the Harrisburg, PA Metaswitch switch. This will occur on or after September 1, 2023.

Table A

	FROM	ТО		
Entity	Harrisburg- 290MD	Harrisburg-29PS0		
CLLI	HRBGPA290MD	HRBGPA29PSO		
Product	POI	METASWITCH		
Point Code	218-102-007	218-102-201		
NXX Type	EOC	EOC		
OCN	0096	0096		
Rate Center Lata	136	136		
State	PA	PA		

Table B

NPA	NXX	TYPE	Switch
717	461	EOC	HRBGPA290MD

Network Changes and Trunk Rearrangements:

The Harrisburg PA PEO switch will be the recipient office of traffic migrated from the

Harrisburg PA POI. Traffic bound for the codes listed in Table B will be delivered via the Lewisberry PA Tandem (LWBYPAXL72T Inter-Lata FG Access SHA) and Harrisburg PA Tandem (HRBGPAHA72T Intra-Lata SHA).

After all traffic is migrated off the Harrisburg PA POI it will be retired and removed from the network.

Carrier Customer Bulletin



FRONTIER COMMUNICATIONS PARENT, INC 401 MERRITT 7 CORPORATE PARK NORWALK CT 06851

Description of Reasonably Foreseeable Impact of the Planned Changes (cont.):

CLECs, IXCs, ILECs, wireless carriers and paging carriers will need to secure new trunk groups built to the Harrisburg Tandem or have existing trunk groups to that switch augmented. IXC Carriers that have direct end office trunks (DEOT) with access connectivity in the Harrisburg PA 290MD POI will be required to reposition the codes to the LWBYPAXL72T and all other CLECs and ILECs to the HRBGPAHA72T.

All ASRs (Access Service Requests) for the Lewisberry or Harrisburg Tandem switch must be received no later than September 1, 2023, to provide sufficient time to migrate the traffic described above. All traffic must be moved by October 1, 2023. All ASRs for the Lewisberry or Harrisburg Tandem switch must carry the project code of HRBGPA290MD.

Please adhere to industry standards using normal procedures that pertain to updates and changes to the LERG for all NXXs subject to the retirement of the Harrisonburg, PA 290MD POI.

If you have questions regarding the information provided in this notice or would like to schedule a meeting with Frontier's Network Engineering and Planning personnel, please contact Lee Abrams @ 518-773-6073.

We look forward to working with your team to enable uninterrupted service during the network redesign and transitioning of your traffic.

For further assistance, please contact your Frontier Account Manager. Public Notice Available on our website at:

https://wholesale.frontier.com/notifications-and-news